villages of Hosdurga, Arsikere and Tiptur Taluks. Much difficulty is experienced in carting them as there is not a feeder road to the Tiptur-Huliyar road. It is therefore suggested that a feeder road may be opened from Hosdurga to Honnavalli.

Reply of Government.—This will be referred to the District Board.

SUBJECT No. 498.

Parapet walls for the road running over Palavalli tank bund.

Mr. Adirajappa, Pavagada Taluk.

Summary of discussion.—Tumkur-Bellary road runs over the Palavalli tank bund in the Pavagada Taluk where it is very narrow and zig-zag, the bund is very steep and is dangerous to the carts passing over it. It is requested therefore that parapet walls on both sides of the road may be ordered to be constructed.

Reply of Government.—This will be referred to the Public Works Department.

SUBJECT No. 499.

Capacity of the Kunigal tank to be increased.

Mr. Herur Gundappa, Kunigal Taluk.

Summary of discussion.—The water stored in the Kunigal tank has to feed the anès of Chatnahalli and Nademavinapura and the seven serial tanks of Amritur, etc. It is requested that early steps may be taken to raise the level of the kodi by two feet and the height of the bund by three feet. Some lands are waste and some lands have been reduced to dry. A project was prepared in Sir Sheshadri Iyer's time.

Reply of Government.—Reported upon adversely by the Chief Engineer.

SUBJECT No. 500.

Pipes for the main and distribution channels of the Kunigal tank.

Mr. Herur Gundappa, Kunigal Taluk.

Summary of discussion.—As the main and distribution channels of the Kunigal tank are not in good repair, much of the water is wasted. It is therefore requested that pipes may be ordered to be laid to conserve and make a fair distribution of water.

Reply of Government.—The matter will be referred to Public Works Department for report.

SUBJECT No. 501.

Feeder channel to Dipambudhi tank.

Mr. Herur Gundappa, Kunigal Taluk.

Summary of discussion.—The Dipambudhi tank has not got good feeders. If an ane is constructed across Kudluthore, there is a certainty of replenishing the tank during the floods and of expanding wet cultivation.

Reply of Government.—This cannot be done.

SUBJECT No. 502.

A feeder to Keachaganpura tank.

Mr. Herur Gundappa, Kunigal Taluk.

Summary of discussion.—Before the Herur tank breached, its kodi water was feeding the Kenchagalpura tank and that water is now going to waste. It is therefore requested that a feeder may be excavated to divert this water to feed the tank referred to above.

Reply of Government.—The matter will be referred to Pucbli Works Department for report.